Approved For R. SERVICE

1028 - 33rd St. N. W.

3307-11 M St., N. W.

Phone: MI. 1647

Phone: MI. 1646

WASHINGTON 7, D. C.

MEMORANDUM

MO	DEL	LICENSE NO		SERIA	L NO.			TOMO	
-8.	· D	KS_							
	PARTS NE	ECESSARY AND EST	IMATE OF LABOR REQUIRE	D PAINT CO		PARTS CO	TE	ESTI	MAT
						7 7	13	6	9
						9 9		-	-
						13 7	3	10	5
						- :	6	4	- (
						1/6	, 6	/	2
						2	7 -2	د	4
						1	29	==	
						11	5-77		7
								-	
								6	-
								2	ζ,
								and an	
								3	(
								3 E	(
								3	(
			<i>T</i>					3 E	(
P o		7 20.00	Do		,			3	
Re	leus	L new	Pandin grav					3	
Re.	leur	Lnew	Pandin grav		50			3	
Re. DI	leur	Lnew	Pandin gran					3	
Re. DI	leure	L new	Paula grav					3	
	leus	L new	Pandin gran					3	
	leur	L'new	Pandin gran					3	
	leus	L'new	Pandin gran				73.	3612	

The above is an estimate axed 50 burelesection and 550 hot Civer my sadded at 4500 by 1000 which has be required after the work has been opened up. Occasionally after the work has started damaged or broken parts are discovered which are not evident the first inspection. Because of this the above prices are not guaranteed.

FORM 129 COMPONY SECTION OF 1000 WHEN THE PROPERTY CO. 37 1000 WHEN THE

Approved For ARLING ARLING	e St. Tel. Ox RLINGTON, V	ord 1//4	- Ower	s 1656	·	Serve Signal	e della di Colore di		· Professor	
		· 7		· /	,	(1 m) (1 m ガー (1 f 析: 小学7)	SCT / Ber	Gar.		ja ja
CIA	ADDRE	8						DATE 9-2	9-49	>
TOTAL 21 0 YEAR US		MILEAGE	·	MOTOR	No.			SERIAL	No.	
SURED BY ADJUSTER		INSPECTOR		!		н	HONE			
DESCRIPTION OF REPAIRS AND REPL	ACEMENTS			RTS		LAB	l l	PAINT		TAL
1	4	NUI	MBER	АМО		AMO		AMOUN'	AMO	TNUO
Rosslace L F 144 C	gje.		-	2	٠٥٠	4	<		-	_
1 LF Invest	er			21	00	14	၁ပ			
11 L Head lang	rassmy			14	20	4	C			
11 L parking 1	annan	بيو		6	00	1	So			
11 L F Quest D	1	1		2	00	m	6			
11 Latin 8	1 Parly	11/1	,		50	1	00			
1 Hood Hunge	faces of	me		2	70	1)				+
11 Front 1/100	201		·			7.	00			+
Phone intras	uf fil			4	35-	7.	20		_	+
Sh & align fro	130	esupe	-			4.	50			_
align front and	Set C	46	. •		3	12	30		1	
fault non &	lep po	21/1				12	30			
	01					18	50			
			1	65.	10					
	. 181	's non	14	6	5.7					
	ers 18/	01	<u> </u>	r-a	49					
TL	<u> </u>			1					-	+
								}	+	+
				A	11	8,				+
				11	ļ					-
The state of the s			<	<u> </u>	-		<u> </u>			\perp
Visiting at their					ļ					\bot
The state of		Andrew Arthurs St. Ac.	TOTAL							
The above is an estimate based on our inspection of cover any additional parts or labor which may be required.	ired after the									
work has been opened up. Occasionally after the work worn or damaged parts are discovered which are not enfirst inspection. Because of this view appears and are far immediate acceptance only.	vident on the		TAX							十

11-9

Bodies and Fenders Straightened, Duco and Enamel Reginishing
Frame Straightening and
Whool Balancing
Tops, Slip Covers and Upholstering

ADDRESS: CENTRAL INTELLIGENCE AGENCY DATE 9/27/49

License No. U.S. _____ Make and Model 1948 Chevrolet

Replace L F fender	LABOR	PARTS
Manage W & Tendol	4 10 00	
Lert head lamp downlate	8 12.00	\$ 21.50
· · · · · · · · · · · · · · · · · · ·		16.40
4 hub can	5.00	12.50
" left parking 1		2.15
sta front bumper and brackets		6.00
a support and pradicate	4.00	\$ 58.55
gravel shield	5.00	A 20*20
hood alighment	3.00	
Figure Dack Danual		
L F Wheel	2.00	
Raint reprint	4.00	
paint repaired parts	6.50	
Autor Serios	9.00	
	60.60	
•	58.65	
	\$100-05	

Estimate bys Co De Frank

Approved For Release 2002/05/06 : CIA-RDP57-00384R001300080111-9

FULL DIA I